

Jack Harrington

From: John Caldwell
Sent: Thursday, August 6, 2026 8:58 AM
To: Derek Soderquist
Cc: Jack Harrington
Subject: RE: pic

Good morning,

Yes, they will need a permit, also the asphalt shingles and what they used for the transition will need to be verified that they can be used together. Most of the time they do not.

Thanks,

John Caldwell
Assistant Building Official
Department of Safety & Inspections
375 Jackson Street
Suite 220
Saint Paul, MN 55101
P: (651) 266-9027
Email: John.Caldwell@ci.stpaul.mn.us
www.StPaul.gov



SAINT PAUL
MINNESOTA

From: Derek Soderquist <Derek.Soderquist@ci.stpaul.mn.us>
Sent: Thursday, August 6, 2026 8:50 AM
To: John Caldwell <John.Caldwell@ci.stpaul.mn.us>
Cc: Jack Harrington <Jack.Harrington@ci.stpaul.mn.us>
Subject: FW: pic

John,
Please see below. Are you in agreement that this work would have required a permit?
Thanks,
Derek

City of Saint Paul

Derek Soderquist
Building Inspector
Department of Safety & Inspections
375 Jackson Street
Suite 220
Saint Paul, MN 55101
P: (651) 266-1934

Email: Derek.Soderquist@ci.stpaul.mn.us
www.StPaul.gov



SAINT PAUL
MINNESOTA

From: Jack Harrington <Jack.Harrington@ci.stpaul.mn.us>
Sent: Thursday, August 6, 2026 8:42 AM
To: Derek Soderquist <Derek.Soderquist@ci.stpaul.mn.us>
Subject: FW: pic

Thank you,

City of Saint Paul

Jack Harrington
Fire Safety Inspector II

Pronouns: He/Him
Department of Safety & Inspections
375 Jackson Street
Suite 220
Saint Paul, MN 55101
P: (651) 266-9142
Email: Jack.Harrington@ci.stpaul.mn.us
www.StPaul.gov



SAINT PAUL
MINNESOTA

From: Greg Heck <GregH@hla.cpa>
Sent: Wednesday, August 5, 2026 1:59 PM
To: Jack Harrington <Jack.Harrington@ci.stpaul.mn.us>
Subject: FW: pic

Think Before You Click: This email originated outside our organization.

ATTACHED IS THE PICTURES OF THE ROOF REPAIRS THAT WERE MADE, THE FIRST 3 WERE THE OVERLAY MEMBRANE WAS LAID AND THEN THE ADHESIVE THAT WAS USED IS THE 4TH PICTURE, LEAKBARRIER WAS THE MEMBRANE PRODUCT USED , THE MATERIAL COSTS WERE LIKE 651 AND I PAY CHAVO A FEE TO MAINTAIN THE BUILDING. THE ESTIMATED TIME TO REPAIR WAS LIKE 3 HOURS SO THAT WAS 100 DOLLARS OF LABOR . HE HAS MAINTAINED BUILDING FOR 15 YEARS AND WAS EXPERIENCED IN USING THIS PRODUCT ON OTHER BUILDING HE MAINTAINS

From: Greg Heck <GregH@hla.cpa>
Sent: Wednesday, August 5, 2026 1:22 PM
To: Greg Heck <GregH@hla.cpa>
Subject: FW: pic

From: Molly Nelson <mollyn@hla.cpa>
Sent: Wednesday, August 5, 2026 1:21 PM
To: Greg Heck <GregH@hla.cpa>
Subject: pic

Thank you,

*Molly Nelson
563 Phalen Blvd
St. Paul, MN 55130
651-251-4371
651-481-0982 (Fax)*

[Click here](#) to upload files.

To pay your invoice:
[Pay \(cardpointe.com\)](https://cardpointe.com)

**NOTICE TO CUSTOMERS PAYING
WITH CREDIT CARD:**

We impose a surcharge of 3.0% when paying with a credit card, which is not greater than our cost of acceptance. The adjustment will appear on your receipt. We do not surcharge debit cards. Any purchases made with a debit card or cash will not include a surcharge.



CONFIDENTIALITY NOTICE: This e-mail and any files transmitted with it are intended solely for the use of the individual or entity to whom they are addressed and may contain confidential and privileged information protected by law. If you received this e-mail in error, any review, use, dissemination, distribution, or copying of the e-mail is strictly prohibited. Please notify the sender immediately by return e-mail and delete all copies from your system.