



Saint Paul Fire Department
645 Randolph Avenue
Saint Paul, MN 55102
(651) 224-7811

Fire Incident Print Report

Incident Location

Dispatch Incident Number: SPFD260808039695
Incident Location: 71 MANITOBA Avenue
City, State, Postal Code: Saint Paul, MN 55117-

Incident Location Use

Location Use Type: Residential - Detached Single Family Dwelling
Incident Location In Use: Yes
Location Used as Intended: Yes

Incident Details

Primary Incident Type: Fire - Structure Fire - Structural Involvement
Primary Station: Station #8 (08) **Shifts or Platoon:** A
District: D2
People Present: Yes

Incident Actions

Incident Action Taken: Salvage And Overhaul; Suppression - Structural Fire Suppression - Exterior; Command and Control - Incident Assessment Completed; Command and Control - Establish Incident Command

Incident Timeline

Alarm: 08/08/2026 12:52:29
First Unit Arrival : 08/08/2026 12:55:21
Incident Clear: 08/08/2026 13:26:56
In Service Date Time: 08/08/2026 13:26:56

Unit Response

Incident Unit Responses

Unit Call Sign	Dispatch Time	Enroute to Scene	Canceled Enroute Time	On Scene Time	Clear Time
E22	12:52:29	12:53:50		12:55:21	13:26:56
E17	12:52:29	12:54:30	12:59:31		12:59:31
E4	12:52:29	12:52:57	12:57:35		12:57:35
L22	12:52:29	12:53:50		12:55:22	13:24:54
L6	12:52:29	12:54:40	12:57:32		12:57:32
S1	12:52:29	12:52:36		12:57:10	12:58:54
M20	12:52:29	12:54:07	12:56:05		12:56:05
C2	12:52:29	12:53:16		12:59:34	13:24:11
C3	12:52:29	12:53:29		12:58:35	13:00:31
CAR5	12:52:29	12:53:49		13:01:28	13:07:57
CAR20	12:52:29	12:53:43		13:01:41	13:26:01
R3	12:52:29	12:53:33	12:58:55		12:58:55
CAR51	12:53:51	12:53:51	12:58:01		12:58:01
M18	12:55:07	12:55:07	12:57:41		12:57:41

Fire Details

Fire Location Type:	Structure		
Fire Water Supply:	Tank Water		
Fire Suppression Appliance:	Small Diameter Fire Hose		
Fire Arrival Condition:	Smoke Fire Showing	Fire Progression Evident:	Yes
Fire Room Of Origin Type:	Balcony Porch Deck	Fire Floor Of Origin:	1
Fire Damage Type:	Moderate Damage		
Fire Investigation Needed:	Yes	Fire Investigation Type:	Investigated By Arson Fire Investigator
Structure Fire Cause:	Smoking Material Illicit Drugs		

Smoke Alarms

Smoke Alarm Presence:	Present
Smoke Alarm Type:	Hardwired
Smoke Alarm Working:	Yes
Smoke Alarm Operation:	Insufficient Source to Activate Alarm

Fire Alarms

Fire Alarm Presence: Not Present

Incident Narratives

Primary Narrative: Dispatched for a porch fire reported by occupants. Ladder 22 and Engine 22 arrived on scene to find a medium sized, two and a half story single family dwelling with smoke coming from the A/D porch corner and a small amount of

fire present and with the occupant working to extinguish the fire with a garden hose. Ladder 22 assumed command. Engine 22 and Ladder 22 used the garden hose and foam/water extinguishers initially to extinguish any remaining fire and began overhaul. No extension into the interior of the residence. Ladder 22 reported that the fire was out and that Ladder 22 and Engine 22 could handle. District Chief 2 approved that order but continued and also continued Car 20-Fire Investigator Leier. Chief 2 arrived and assumed command.

Car 20-Investigator Leier arrived and began their investigation. Engine 22 and Ladder 22 completed overhaul of the front porch in coordination with Car 20 and foamed the remaining structure and overhauled debris using a bumper hose line. No ventilation or search needed. Car 20 completed their investigation. All companies released and command terminated.

Other Alarms

**Other Alarm
Presence:**

Not Present

Incident Authorization

**Member Making
Report - Signature:**

Aspnes, Michael

**Officer in Charge -
Signature:**

Aspnes, Michael