

From: [Palm, Michael \(CI-StPaul\)](#)
To: [Doody, Melissa \(CI-StPaul\)](#)
Subject: 823 Englewood
Date: Friday, October 2, 2020 8:04:38 AM
Attachments: [image002.png](#)
[image003.png](#)
[image004.png](#)

Basement bedroom - No egress window, It does have a door that goes to a stairway that goes directly out the rear side of the house. It also has No heat in the room but it does have a hot water heater in the closet.

Main floor looked ok.

2nd floor has a bedroom with No heat in the room rear side of the house. Bathroom has questionable height problems.

I will send you pictures of the place that I took.

I will also send you the other trades findings.

Mike



Michael Palm

Sr. Building Inspector

Dept of Safety and Inspections

375 Jackson St. Suite 220

Saint Paul, MN 55102

P: 651-266-9025

C: 651-248-9025

F: 651-266-9099

michael.palm@ci.stpaul.mn.us



Making Saint Paul the Most Livable City in America

“DSI’s Mission: To preserve and improve the quality
Of life in St. Paul by protecting and promoting
Public health and safety for all.”