

Date: November 20, 2015
File #: 12 - 213970
Folder Name: 706 CONWAY ST
PIN: 322922410067

HP District: HPL-DB
Property Name: Frank & Hattie Davis House
Survey Info: RA-SPC-2445



Date: November 20, 2015
File #: 12 - 213970
Folder Name: 706 CONWAY ST
PIN: 322922410067

HP District: HPL-DB
Property Name: Frank & Hattie Davis House
Survey Info: RA-SPC-2445



Date: November 20, 2015
File #: 12 - 213970
Folder Name: 706 CONWAY ST
PIN: 322922410067

HP District: HPL-DB
Property Name: Frank & Hattie Davis House
Survey Info: RA-SPC-2445



Date: November 20, 2015
File #: 12 - 213970
Folder Name: 706 CONWAY ST
PIN: 322922410067

HP District: HPL-DB
Property Name: Frank & Hattie Davis House
Survey Info: RA-SPC-2445



Date: November 20, 2015
File #: 12 - 213970
Folder Name: 706 CONWAY ST
PIN: 322922410067

HP District: HPL-DB
Property Name: Frank & Hattie Davis House
Survey Info: RA-SPC-2445



Date: November 20, 2015
File #: 12 - 213970
Folder Name: 706 CONWAY ST
PIN: 322922410067

HP District: HPL-DB
Property Name: Frank & Hattie Davis House
Survey Info: RA-SPC-2445



Date:
File #:
Folder Name:
PIN:

November 20, 2015
12 - 213970
706 CONWAY ST
322922410067

HP District:
Property Name:
Survey Info:

HPL-DB
Frank & Hattie Davis House
RA-SPC-2445

Date:
File #:
Folder Name:
PIN:

November 20, 2015
12 - 213970
706 CONWAY ST
322922410067

HP District:
Property Name:
Survey Info:

HPL-DB
Frank & Hattie Davis House
RA-SPC-2445

A photograph showing the interior of a room, specifically the ceiling. The ceiling is a mottled yellowish-brown color and is covered with hundreds of small, dark, circular holes, suggesting a severe pest infestation, possibly termites. A single, simple light bulb is hanging from the ceiling in the center-left area. The walls below the ceiling appear to be made of horizontal wooden planks or slats.

A photograph of a wooden structure, likely a wall or a partition, made of horizontal wooden slats. The wood is dark brown and shows significant signs of decay, including missing slats, peeling wood, and exposed areas. A small, blue and white object, possibly a piece of debris or a small container, is visible on the lower part of the structure. A thin, dark wire or cable runs vertically along the right side of the structure.

Date: November 20, 2015
File #: 12 - 213970
Folder Name: 706 CONWAY ST
PIN: 322922410067

HP District: HPL-DB
Property Name: Frank & Hattie Davis House
Survey Info: RA-SPC-2445



Date: November 20, 2015
File #: 12 - 213970
Folder Name: 706 CONWAY ST
PIN: 322922410067

HP District: HPL-DB
Property Name: Frank & Hattie Davis House
Survey Info: RA-SPC-2445



Date: November 20, 2015
File #: 12 - 213970
Folder Name: 706 CONWAY ST
PIN: 322922410067

HP District: HPL-DB
Property Name: Frank & Hattie Davis House
Survey Info: RA-SPC-2445

