

WORK PLAN - BREAKDOWN COST OF REHABILITATION

(To be done in accordance with the Code Compliance Inspection Report) Address: 1762 Englewood Avenue, St. Paul

[illegible]

* The plumbing contractor, Focus Plumbing Services, LLC, has advised that a "buffer time period should be considered in the event that the general labor work itemized above is not timely as expected; this general labor work to be completed the week of 7/14/2025.

Total Project Cost: (approx.) \$ 8,250

Note: (Code Enforcement Officers estimate the cost to repair this structure is \$ _____ to \$ _____)