

Space heater, open wall in unit 2.




Disassembled radiator shielding
in unit 2 livingroom




Space heater in unit 2 bathroom.



Disassembled radiator shielding
in unit 2 kitchen




Temperature in living room of
Unit 1



Unit 1 temp in Kitchen.





Complaint of a moldlike substance under the bathroom sink in unit 1.

Thermostat in Unit 1 showing temp is 68 degrees with use of 2 space heaters

